

**Smoking Airplanes®
Smoke System Kits**



And VCAS™

(Visual Collision Avoidance System)

www.smokingairplanes.com / john@smokingairplanes.com

4021 Stetson Ave. -- Rosamond, CA 93560 • 661-713-9050

MANDATORY SERVICE BULLETIN

NUMBER: SB-06-002

DATE ISSUED: September 21, 2006

APPLIES TO: Oil Fill Cap Gaskets from Invoice No. 1150 through 1202

Synopsis: There have been recent reports of Oil Fill Cap Gasket swelling and premature deterioration. Testing of the latest batch of gaskets revealed that inferior material was used by the gasket manufacturer (who has since gone out of business). Failure of the fill cap gasket could result in the escape of smoke oil from the oil tank.

Required Action: **Immediately and/or before your next flight**, install the Fill Cap Gasket supplied. Simply remove your fill cap from your oil tank, remove the existing gasket from the cap and replace it with the new gasket. No further action is required other than normal inspections as outlined in INSTRUCTIONS FOR CONTINUED AIRWORTHINESS in your INSTALLATION AND OPERATION INSTRUCTION MANUAL.

Please forward this Service Bulletin and material to the new owner if aircraft was sold or otherwise transferred (or contact Smoking Airplanes with transfer information).
